

Lead Service Line (LSL) Inventory

PWS ID (OR41####)	OR4100608
PWS name	OTTER ROCK WATER DISTRICT
Operator submitting report	BETH ELLIKER
Date completed	10/14/24
Has lead pipe ever been documented in the water system service lines?	No



color key
 Black - required
 Blue: monitoring location determinations
 Green: good to know
 Purple: calculated by spreadsheet - do not edit

Summary	
Lead	GRR
0	0

GRR=Galvanized requiring replacement

Required for Lead service line inventory

Site ID	Location Identifier (Required for Lead and GRR status only - optional for other service lines)	Water system owned service line current material	Water System service line material identification method	Customer owned service line current material	If customer service line is galvanized, was upstream service line material ever lead?	Customer service line material identification method
	120 1st St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	125 1st St	Non-lead - unk - post 1985	Records only	Non-lead - unk - post 1985	No	Records only
	125 Mahala Way	Non-lead - unk - post 1985	Records only	Non-lead - unk - post 1985	No	Records only
	140 Mahala Way	Non-lead - unk - post 1985	Records only	Non-lead - unk - post 1985	No	Records only
	145 3rd St	Non-lead - unk - post 1985	Records only	Non-lead - unk - post 1985	No	Records only
	145 Mahala Way	Non-lead - unk - post 1985	Records only	Non-lead - unk - post 1985	No	Records only
	155 3rd St	Non-lead - unk - post 1985	Records only	Non-lead - unk - post 1985	No	Records only
	155 4th St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	160 3rd St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	165 3rd St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	165 4th St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	220 3rd St	Non-lead - unk - post 1985	Records only	Non-lead - unk - post 1985	No	Records only
	220 4th St	Non-lead - Plastic	Statistical - inspected	Non-lead - Plastic	NA - not galvanized	Statistical - inspected
	225 3rd St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	225 4th St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	230 1st St	Non-lead - Plastic	Statistical - inspected	Non-lead - Plastic	NA - not galvanized	Statistical - inspected
	235 4th St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	240 3rd St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	240 4th St	Non-lead - Plastic	Statistical - inspected	Non-lead - Plastic	NA - not galvanized	Statistical - inspected
	265 1st St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	315 1st St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	315 4th St	Unknown	Statistical - not inspected	Unknown	Unknown	Statistical - not inspected
	319 1st St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	320 3rd St	Non-lead - unk - post 1985	Records only	Non-lead - unk - post 1985	No	Records only
	325 3rd St	Unknown	Statistical - not inspected	Unknown	Unknown	Statistical - not inspected
	330 1st St	Unknown	Statistical - not inspected	Unknown	Unknown	Statistical - not inspected
	333 4th St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	410 1st St	Unknown	Statistical - not inspected	Unknown	Unknown	Statistical - not inspected
	415 1st St	Non-lead - Plastic	Statistical - inspected	Non-lead - Plastic	NA - not galvanized	Statistical - inspected
	425 3rd St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	515 1st St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	520 1st St	Unknown	Statistical - not inspected	Unknown	Unknown	Statistical - not inspected
	525 1st St	Unknown	Statistical - not inspected	Unknown	Unknown	Statistical - not inspected
	615 2nd St	Non-lead - Plastic	On site inspection only	Non-lead - Plastic	NA - not galvanized	On site inspection only
	615 3rd St	Non-lead - unk - post 1985	Records only	Non-lead - unk - post 1985	No	Records only
	620 1st St	Unknown	Statistical - not inspected	Unknown	Unknown	Statistical - not inspected
	6225 C Ave	Unknown	Statistical - not inspected	Unknown	Unknown	Statistical - not inspected

Site ID	Location Identifier (Required for Lead and GRR status only - optional for other service lines)	Water system owned service line current material	Water System service line material identification method	Customer owned service line current material	If customer service line is galvanized, was upstream service line material ever lead?	Customer service line material identification method
	6240 C Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	625 1st St	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6250 C Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6252 C Ave	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6260 C St	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	6275 C Ave	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	630 3rd St	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6310 A Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6315 B Ave	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	6320 B Ave	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	6325 B Ave	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	6330 Nellie Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6340 A Ave	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6410 A Ave	Non-lead – Copper	On site inspection only	Non-lead – Copper	NA – not galvanized	On site inspection only
	6410 C Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6415 A Ave	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6420 B Ave	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6420 Nellie Ave	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6425 B Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6435 A Ave	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6440 Gladys Ave	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6515 A Ave	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6515 B Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6515 Gladys Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6520 A Ave	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	6520 B Ave	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6520 Otter Crest Lp	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6525 A Ave	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6525 Nellie Ave	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6540 A Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6545 A Ave	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6545 B Ave	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6610 Otter Crest Lp	Non-lead – 2+ inches	Records only	Non-lead – 2+ inches	No	Service Line > 2
	6615 Nellie Ave	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6625 Ellie Ave	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6625 Gladys Ave	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6625 Otter Crest Lp	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6630 A Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6630 Gladys Ave	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6630 Otter Crest Lp	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	6635 Ellie Ave	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6635 Gladys Ave	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	6635 Otter Crest Lp	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6640 Ellie Ave	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6640 Gladys Ave	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6640 Nellie Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6645 Otter Crest Lp	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only

Site ID	Location Identifier (Required for Lead and GRR status only - optional for other service lines)	Water system owned service line current material	Water System service line material identification method	Customer owned service line current material	If customer service line is galvanized, was upstream service line material ever lead?	Customer service line material identification method
	6650 A Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6650 Nellie Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6650 Otter Crest Lp	Copper	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6655 Ellie Ave	Non-lead – Plastic	On site inspection only	Non-lead – Copper	NA – not galvanized	On site inspection only
	6660 A Ave	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6665 A Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6680 A Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6715 Gladys Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6715 Otter Crest Lp	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6720 Gladys Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6720 Otter Crest Lp	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6725 Ellie Ave	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6725 Gladys Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6735 Gladys Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6740 Ellie Ave	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6740 Gladys Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6750 Ellie Ave	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	6750 Gladys Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6758 Gladys Ave	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6760 Gladys Ave	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	6805 Boland Wy	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6810 Gladys Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6811 Boland Wy	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6815 Gladys Ave	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6820 Gladys Ave	Non-lead – Copper	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	6820 Mahala Ct	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6825 Boland Wy	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6830 Ellie Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6830 Gladys Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6835 Ellie Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6840 Boland Wy	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6850 Ellie Ave	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	6851 Ellie Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6855 Ellie Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6855 Gladys Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6860 Mahala Ct	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	6865 Boland Wy	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6865 Ellie Ave	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6865 Gladys Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6875 Ellie Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6875 Gladys Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6885 Otter Crest Lp	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	6895 Ellie Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6910 Otter Crest Lp	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	6911 Ellie Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6921 Ellie Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	6928 Gladys Ave	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected

Site ID	Location Identifier (Required for Lead and GRR status only - optional for other service lines)	Water system owned service line current material	Water System service line material identification method	Customer owned service line current material	If customer service line is galvanized, was upstream service line material ever lead?	Customer service line material identification method
	7045 Otter Crest Lp	Non-lead – 2+ inches	Records only	Non-lead – 2+ inches	No	Service Line > 2
	710 1st St	Non-lead – Copper	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	710 3rd St	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	715 4th St	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	725 4th St	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	730 3rd St	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only
	730 4th St	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	740 3rd St	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	745 3rd St	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	747 4th St	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	750 4th St	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	755 3rd St	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	755 4th St	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	765 1st	Non-lead – 2+ inches	Records only	Non-lead – 2+ inches	No	Service Line > 2
	765 3rd St	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	815 1st St	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	820 2nd St	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	825 1st St	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	830 3rd St	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	832 2nd St	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	835 1st St	Non-lead – Plastic	Statistical – inspected	Non-lead – Plastic	NA – not galvanized	Statistical – inspected
	835 2nd St	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	845 1st St	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	90 3rd St	Non-lead – unk – post 1985	Records only	Non-lead – unk – post 1985	No	Records only
	915 1st St	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	925 1st St	Unknown	Statistical – not inspected	Unknown	Unknown	Statistical – not inspected
	95 3rd St	Non-lead – Plastic	On site inspection only	Non-lead – Plastic	NA – not galvanized	On site inspection only